


FIG. 1



[illegible]

FIG. 4A




FIG. 4B




FIG. 5




FIG. 6




FIG. 8

		OM		FS		SS1/2		SS1/4		SS1/8		SS1/16	
		CF		1/2f		1/4f		1/8f		1/16f		1/32f	
		Px	SL	L1	L2	L1	L2	L1	L2	L1	L2	L1	L2
G&1	G%1	G1	g1	P1	L1	1	1	1	1	1	1	1	1
				P2	L2	1	0	0	0	0	0	0	0
			g2	P3	L2	1	1	0	0	0	0	0	0
				P4	L1	1	0	0	0	0	0	0	0
		G2	g3	P5	L2	1	1	1	1	0	0	0	0
				P6	L1	1	0	0	0	0	0	0	0
			g4	P7	L1	1	1	0	0	0	0	0	0
				P8	L2	1	0	0	0	0	0	0	0
		G3	g5	P9	L2	1	1	1	1	1	1	0	0
				P10	L1	1	0	0	0	0	0	0	0
			g6	P11	L1	1	1	0	0	0	0	0	0
				P12	L2	1	0	0	0	0	0	0	0
		G4	g7	P13	L1	1	1	1	1	0	0	0	0
				P14	L2	1	0	0	0	0	0	0	0
			g8	P15	L2	1	1	0	0	0	0	0	0
				P16	L1	1	0	0	0	0	0	0	0
	G%2	G5	g9	P17	L2	1	1	1	1	1	1	1	1
				P18	L1	1	0	0	0	0	0	0	0
			g10	P19	L1	1	1	0	0	0	0	0	0
				P20	L2	1	0	0	0	0	0	0	0
		G6	g11	P21	L1	1	1	1	1	0	0	0	0
				P22	L2	1	0	0	0	0	0	0	0
			g12	P23	L2	1	1	0	0	0	0	0	0
				P24	L1	1	0	0	0	0	0	0	0
		G7	g13	P25	L1	1	1	1	1	1	1	0	0
				P26	L2	1	0	0	0	0	0	0	0
			g14	P27	L2	1	1	0	0	0	0	0	0
				P28	L1	1	0	0	0	0	0	0	0
		G8	g15	P29	L2	1	1	1	1	0	0	0	0
				P30	L1	1	0	0	0	0	0	0	0
			g16	P31	L1	1	1	0	0	0	0	0	0
				P32	L2	1	0	0	0	0	0	0	0

FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15

OM		FS				SS1/2				SS1/4				SS1/8			
CF		1/4f				1/8f				1/16f				1/32f			
Px	SL	L1	L2	L3	L4	L1	L2	L3	L4	L1	L2	L3	L4	L1	L2	L3	L4
P1	L1	1				1				1				1			
P2	L2		1				0				0				0		
P3	L3			1			1				0				0		
P4	L4				1			0				0				0	
P5	L2		1				1				1				0		
P6	L3			1				0				0				0	
P7	L4				1				1				0				0
P8	L1	1				0				0				0			
P9	L3			1			1				1				1		
P10	L4				1			0				0				0	
P11	L1	1				1				0				0			
P12	L2		1				0				0				0		
P13	L4				1				1				1				0
P14	L1	1				0				0				0			
P15	L2		1				1				0				0		
P16	L3			1				0				0				0	
P17	L2		1				1				1				1		
P18	L3			1				0				0				0	
P19	L4				1				1				0				0
P20	L1	1				0				0				0			
P21	L3			1				1			1					0	
P22	L4				1				0				0				0
P23	L1	1				1				0				0			
P24	L2		1				0				0				0		
P25	L4				1				1				1			1	
P26	L1	1				0				0				0			
P27	L2		1				1				0				0		
P28	L3			1				0				0				0	
P29	L1	1				1				1				0			
P30	L2		1				0				0				0		
P31	L3			1				1	1			0				0	
P32	L4				1				0				0				0

FIG. 16A




FIG. 16B




FIG. 17




FIG. 18




FIG. 19

		OM		FS				SS1/2				SS1/4				SS1/8				
		CF		1/4f				1/8f				1/16f				1/32f				
		SPx	SL	L1	L2	L3	L4	L1	L2	L3	L4	L1	L2	L3	L4	L1	L2	L3	L4	
G%1	G#1	g1	P1	L1	1				1				1				1			
			P2	L2		1				1				1				1		
			P3	L3			1			0				0				0		
			P4	L4				1			0				0				0	
		g2	P5	L3			1			1				0				0		
			P6	L4				1			1				0				0	
			P7	L1	1				0			0				0				
			P8	L2		1				0			0				0			
	G#2	g3	P9	L3			1			1				1				0		
			P10	L4				1			1				1				0	
			P11	L1	1				0			0				0				
			P12	L2		1				0			0				0			
		g4	P13	L1	1			1			1			0			0			
			P14	L2		1			1			1			0			0		
			P15	L3			1			0			0				0			
			P16	L4				1			0			0				0		
	G#3	g5	P17	L3			1			1				1				1		
			P18	L4				1			1				1				1	
			P19	L1	1				0			0				0				
			P20	L2		1				0			0				0			
		g6	P21	L1	1			1			1			0			0			
			P22	L2		1			1			1			0			0		
			P23	L3			1			0			0				0			
			P24	L4				1			0			0				0		
	G#4	g7	P25	L1	1			1			1			1			0			
			P26	L2		1			1			1			1			0		
			P27	L3			1			0			0			0			0	
			P28	L4				1			0			0				0		
		g8	P29	L3			1			1			0			0			0	
			P30	L4				1			1				0				0	
			P31	L1	1				0			0				0				
			P32	L2		1				0			0				0			

FIG. 20




FIG. 21

OM		FS		SS1/2		SS1/4		SS1/8	
CF		1/4f		1/8f		1/16f		1/32f	
SPx	SL	L1	L2	L3	L4	L5	L6	L7	L8
P1	L1	1	1	1	1	1	1	1	1
P2	L2	1	1	1	1	1	1	1	1
P3	L3	1	1	1	1	1	1	1	1
P4	L4	1	1	1	1	1	1	1	1
P5	L3	1	1	1	1	1	1	1	1
P6	L4	1	1	1	1	1	1	1	1
P7	L1	1	1	1	1	1	1	1	1
P8	L2	1	1	1	1	1	1	1	1
P9	L7	1	1	1	1	1	1	1	1
P10	L8	1	1	1	1	1	1	1	1
P11	L5	1	1	1	1	1	1	1	1
P12	L6	1	1	1	1	1	1	1	1
P13	L5	1	1	1	1	1	1	1	1
P14	L6	1	1	1	1	1	1	1	1
P15	L7	1	1	1	1	1	1	1	1
P16	L8	1	1	1	1	1	1	1	1
P17	L3	1	1	1	1	1	1	1	1
P18	L4	1	1	1	1	1	1	1	1
P19	L1	1	1	1	1	1	1	1	1
P20	L2	1	1	1	1	1	1	1	1
P21	L1	1	1	1	1	1	1	1	1
P22	L2	1	1	1	1	1	1	1	1
P23	L3	1	1	1	1	1	1	1	1
P24	L4	1	1	1	1	1	1	1	1
P25	L5	1	1	1	1	1	1	1	1
P26	L6	1	1	1	1	1	1	1	1
P27	L7	1	1	1	1	1	1	1	1
P28	L8	1	1	1	1	1	1	1	1
P29	L7	1	1	1	1	1	1	1	1
P30	L8	1	1	1	1	1	1	1	1
P31	L5	1	1	1	1	1	1	1	1
P32	L6	1	1	1	1	1	1	1	1

G1

G#1

G2

G#1

G3

G#2

G4

G#2

FIG. 22




FIG. 23

OM		FS				SS1/2				SS1/4				SS1/8			
CF		1/4f				1/8f				1/16f				1/32f			
SPx	SL	L1	L2	L3	L4	L5	L6	L7	L8	L1	L2	L3	L4	L5	L6	L7	L8
P1	L1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P2	L3	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P3	L5	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P4	L7	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P5	L5	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P6	L7	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P7	L1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P8	L3	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P9	L6	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P10	L8	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P11	L2	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P12	L4	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P13	L2	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P14	L4	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P15	L6	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P16	L8	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P17	L5	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P18	L7	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P19	L1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P20	L3	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P21	L1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P22	L3	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P23	L5	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P24	L7	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P25	L2	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P26	L4	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P27	L6	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P28	L8	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P29	L6	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P30	L8	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P31	L2	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
P32	L4	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1